

MARITIME SAFETY COMMITTEE 97th session Agenda item 22 MSC 97/22/Add.1/Corr.1 2 May 2017 Original: ENGLISH

REPORT OF THE MARITIME SAFETY COMMITTEE ON ITS NINETY-SEVENTH SESSION

Corrigendum

ANNEX 5

RESOLUTION MSC.413(97) (adopted on 25 November 2016)

AMENDMENTS TO THE INTRODUCTION AND PART A OF THE INTERNATIONAL CODE ON INTACT STABILITY, 2008 (2008 IS CODE)

1 In the existing paragraph 3 of the annex, the reference to "figure 1", set out in the new paragraph 2.31, is replaced with "figure 2.8-1".

ANNEX 6

RESOLUTION MSC.414(97) (adopted on 25 November 2016)

AMENDMENTS TO THE INTRODUCTION AND PART A OF THE INTERNATIONAL CODE ON INTACT STABILITY, 2008 (2008 IS CODE)

In the existing paragraph 3 of the annex, the reference to "figure 1", set out in the new paragraph 2.31, is replaced with "figure 2.8-1".



ANNEX 7

RESOLUTION MSC.415(97) (adopted on 25 November 2016)

AMENDMENTS TO PART B OF THE INTERNATIONAL CODE ON INTACT STABILITY, 2008 (2008 IS CODE)

In the annex, the existing figure 2.7-1 is replaced with the following:




Figure 2.7.2 – Diagrams showing the intended meaning of parameters α , β , x, y and h. F_t shows the vector of the applied wire tension."